

RP-29-06 ERRATA

If you, as a user of IESNA RP-29-06, *Lighting for Hospitals and Health Care Facilities*, believe you have located an error not covered by the following revisions, you should e-mail your information to Don Mennie at: dmennie@iesna.org or send a letter to: Don Mennie, Technical Editor, IESNA, 120 Wall Street 17th Floor, New York, NY 10005. Additions will be posted to this list as they become available. This errata list was last updated on **August 3, 2007**.

Please confine your comments to specific typographical errors or misstatements of fact in the RP-29-06 text and/or graphics. Do not attempt to revise or update the document itself.

● **Table 4 appearing on page 50**

Illuminance levels presented for three of the task locations listed in Table 4 are in error. The correct values are given below:

Task Location	Lux	Footcandles
Operating Room, surgical table	25000	2500
Operating Room, emergency table	2000	200
Delivery Room, obstetrical table	25000	2500

The 25000 lux (2500 fc) corrections will bring the illuminance recommendations listed in Table 4 into agreement with the illuminance recommendations found in **Section 4.11.1 Operating Room** (see page 18, top of left-hand column); **Section 4.16.3 Delivery Area** (see page 27, bottom of right-hand column), and in the fourth paragraph of **Section 4.17.2.2 General Radiographic/Fluoroscopic Room** (see page 28, bottom of right-hand column).

The 2000 lux (200 fc) correction will bring the illuminance recommendations listed in Table 4 into agreement with the illuminance recommendations found in the third paragraph of **Section 4.17.2.2 General Radiographic/Fluoroscopic Room** (see page 28, right-hand column)